

# Site monitoring report

Please find detailed below the report for the site monitoring undertaken on 19<sup>th</sup> March 2024.

**Site Name:** Barling Landfill, Southend Road, Barling Magna  
**File Ref:** 34 421 15  
**Operator:** Enovert  
**Visit no:** 2  
**Monitoring Officer:** Tom McCarthy      **Tel No:** 03330 320943

## Permissions:

ESS/31/99/ROC: Installation of plant and machinery within a compound to utilise landfill gas for electricity generation  
ESS/36/05/ROC: Permanent installation of LFG flare within existing LFG generation plant  
ESS/51/08/ROC: Review of Old Planning Permission (ROMP) application for permission reference ROC/634/90  
ESS/11/09/ROC: New portable building for use as a manager's office and meeting room in substitution for a permission for two new separate buildings  
ESS/29/10/ROC: Security compound  
ESS/47/10/ROC: Increased surcharging on part of site

## Constraints:

Weather:	<b>Dry</b> / Windy / Rain / Snow
Noise:	<b>Acceptable</b> / Not acceptable / N/A
Approach roads:	Dry / Dusty / <b>Wet</b> / Muddy / Flooded
Ground:	Dry / Dusty / <b>Wet</b> / Damp / <b>Muddy</b> / Flooded
Access:	Obstructed / <b>Not obstructed</b>
Wheel cleaning:	<b>Washer</b> / Spinner / Sweeper / None
Hose:	In use / <b>Not in Use</b>
Machinery:	<b>Working</b> / Not Working
Stockpiles:	Height = <b>Various</b>
Bunds:	<b>Profiled</b> / <b>Grassed</b> / <b>Weeds</b> / <b>Soil</b>

## Inspection results summary:

An area to the north of cells 1 and 2 remains to be restored with the operator proposing to work/infill this area once the weather improves and vehicles can more easily access this part of the site. Once this work is complete, the northern part of the site would then be fully restored and potentially able to put into agricultural use.

Imported material, as detailed in the last monitoring report, is being deposited in a temporary stockpiling area which has been created within areas 5a and 6a. The operator is due to have a site survey undertaken in the coming weeks, from which this part of the site will be pegged out for confirmation of levels. Based on the results of this, the operator will duly spread any overfilling, which has occurred, to the east as part of the natural progression of works.

A few pot holes were noted on the site haul road. However, there was no debris or major staining on the main site access on to Southend Road.

**Compliance with conditions and actions to be taken before next visit:**

- Although not necessarily a specific action in terms of operations – officers expect continued dialogue with the operator in terms of activities occurring on-site. With regard to the pending planning application (ref: ESS/38/16/ROC) officers anticipate a decision being issued on this application shortly, following the submission of additional information in September and December 2023.

**Note: The actions noted in this report are required in order to ensure adequate progress is made and to avoid potential enforcement action against a breach of planning control.**