

Site monitoring report

Please find detailed below the report for the site monitoring undertaken. If you should have any queries or require any photographs taken on, please do not hesitate to contact me.

Site Name: Brightlingsea Quarry (Trinity and Girling)

File Ref: 14 421 01

Operator: Brett Aggregates

Site Representatives: Karol Podkomorzy (Brett)

Visit no: 1 of 2

Date: Wednesday 8th November 2023

Time on site: 14:30

Time off site: 15:00

Monitoring Officer: Tom Sycamore Tel No: 03330 321 896

Site Co-ordinator: Tom Sycamore Tel No: 03330 321 896

Permission no's:

ESS/39/13/TEN – Winning and working of minerals with progressive infilling and restoration to agriculture and nature conservation (completion by 31/01/2026) – variation of ESS/61/12/TEN, ESS/28/03/TEN and ESS/47/94/TEN.

ESS/39/13/TEN/NMA1 – Non-material amendment to allow relocation of site access, weighbridge, site office and car park.

Constraints:

- Weather: Dry/ **Windy** / **Rain** / Snow
- Noise: **Acceptable**/ Not acceptable / N/A
- Approach roads: Dry / Dusty / **Wet** / **Muddy** / Flooded
- Ground: Dry / Dusty / **Wet** / Damp / **Muddy** / Flooded
- Access: Obstructed (locked gate) / **Not Obstructed** / Mud on Road
- Wheel cleaning: Washer / Spinner / Sweeper / none **N/A**

- Hose: In use / **Not in Use** / N/A
- Machinery: Working / **Not working**
- In correct position: **Yes** / No / N/A
- Stockpiles: Height = N/A
- Bunds: **Profiled / Grassed** / Some weeds / NA

Actions from last site visit:

- Revised restoration plan currently under determination by the MPA.

Inspection Results Summary:

- Trinity and Girling inspected (cells A and C).
- Public rights of way and signage in correct locations.
- Trinity landholding has now been restored. Relocated badger set in correct location and land/waterbody brought to the levels as per approved restoration plan.
- Restoration works on Girling landholding largely completed. Island formation within waterbody in place. Trees and hedgerows planted around southern, eastern, northern and western boundaries of the water body. Failed planting is replaced as and when needed.

Permission under 2017 EIA regulations?:

- Yes / **No**

Actions to be taken before next site visit:

- Await outcome of revised restoration plan. Complete restoration, subject to approval.
- Continue maintenance of site and replacement of failed planting.

Note: The actions noted in this report are required in order to ensure adequate progress is made and to avoid potential enforcement action against a breach of planning control.