

# Site monitoring report

Please find detailed below the report for the site monitoring undertaken. If you should have any queries or require any photographs taken on, please do not hesitate to contact me.

**Site Name:** Wivenhoe Quarry (area west of Keelars Lane), Alresford Road, CO79JU

**File Ref:** 14.421.27

**Operator:** Tarmac

**Site Representative:** Polly Baines (Tarmac)

**Visit no:** 2 of 2

**Date:** 20<sup>th</sup> March 2024

**Time on site:** 10:30am

**Time off site:** 12pm

**Monitoring Officer:** Shelley Bailey                      Tel No: 03330136824

**Site Co-ordinator:** Shelley Bailey                      Tel No: 03330136824

## Permission no's:

ESS/80/20/TEN – Continuation of quarry restoration to part agriculture, part nature conservation and part open water, without compliance with conditions 1 (approved plans), 44 (landscape scheme), 49 (completion by 30<sup>th</sup> June 2020), 50 (restoration by 30<sup>th</sup> June 2020) and 53 (Construction Environment Management Plan) attached to planning permission ref ESS/43/19/TEN to allow for an extension of time to complete restoration and for the permanent retention of the access onto Alresford Road.

## Constraints:

- Weather:                      **Dry/ Windy / Rain / Snow**
- Noise:                         Acceptable/ Not acceptable / **N/A**
- Approach roads:            Dry / Dusty / **Wet / Muddy / Flooded**
- Ground:                        Dry / Dusty / **Wet / Damp / Muddy / Flooded**
- Access:                         **Gate usually locked**
- Wheel cleaning:             Washer / Spinner / Sweeper / none **N/A**

- Hose: In use / Not in Use / **N/A**
- Machinery: Working / Not working **N/A**
- In correct position: Yes / No / **N/A**
- Stockpiles: Height = **N/A**
- Bunds: Profiled / Grassed / Some weeds / **N/A**

**Actions from last site visit:**

- Alresford Road access works to be finalised and submitted for approval.
- Poned area alongside Keelars Lane restored tunnel to be regularised.

**Inspection Results Summary:**

- Alresford Road access works have not progressed. Tarmac are still undecided as to the scheme they want to implement. This does need to be finalised as a matter of priority.
- The ponded area alongside the Keelars Lane restored tunnel is in place but has not been regularised.
- The site generally was holding a lot of water, with some areas flooded.
- The site has varying sizes of debris across the restored surface. Permission ref ESS/80/20/TEN requires no debris larger than 15cm in diameter. Stones should be picked across such that this is adhered to.

**Actions to be taken before next site visit:**

- Alresford Road access works to be finalised and implemented.
- Poned area alongside Keelars Lane restored tunnel to be regularised.
- Surface stones to be picked.
- Tarmac to ensure that all seeding and planting has been carried out in accordance with the restoration plan, prior to the first aftercare visit.

**Note: The actions noted in this report are required in order to ensure adequate progress is made and to avoid potential enforcement action against a breach of planning control.**